## **ASBESTOS SURVEY**

Westlink Library 8515 W. Bekemeyer Wichita, Kansas

#### **PREPARED FOR:**

City of Wichita 455 N Main Wichita, KS 67202

#### **PREPARED BY:**

Paradigm Group, LLC PO Box 8200 Wichita, KS 67208 316.239.7097

October 5, 2023



October 5, 2023

City of Wichita 455 N Main Wichita, KS 67202

RE: Asbestos survey – Westlink Library, 8515 W. Bekemeyer, Wichita, KS.

Per your request, Paradigm Group has completed an asbestos survey of the above referenced property. This survey is for the identification of asbestos-containing materials in buildings that are to be renovated or demolished. Samples were taken of all accessible suspect asbestos containing materials throughout the property. Our laboratory has completed sample analysis and the following asbestos-containing materials were identified:

## Asbestos Containing Materials (>1% Asbestos)

#### Category I Non-Friable

- Approximately 162 sf of asbestos floor tile only. See location map for location of material.
- Approximately 80 sf of blue asbestos stair tread. See location map for location of material.

Note: The above category I non-friable asbestos containing materials <u>do not</u> need to be removed prior to demolition or renovation activities unless applied to concrete that will be recycled or if it will be subject to crushing, crumbling, pulverizing or otherwise rendered friable.

#### Category II Non-Friable

• Approximately 1 sink with asbestos undercoating. See location map for location of material

Note: The above category II non-friable asbestos containing materials must be removed prior to demolition or renovation if it will be subjected to crushing, crumbling, pulverizing or otherwise rendered friable by demolition or renovation activities.

This survey was performed by an EPA accredited inspector and sample analysis was performed by a NVLAP and AIHA accredited laboratory. Paradigm cannot guarantee all asbestos-containing materials were identified due to the possibility that there may be ACM hidden from sight by non-ACM or in inaccessible locations.

This report has been prepared for exclusive use of our client, in accordance with generally accepted

asbestos survey practices, and within the constraints of client's directives. No warranties, either expressed or implied, are intended or made. Conclusions drawn by others from results of this survey, as described in this report, should recognize the limitations of the survey methods.

If you require additional services or have questions, please contact us.


Best regards,

Davin Held

Darin Helsel Inspector

# **Removal Cost Estimate**

It is estimated that it will cost \$1,750.00 to complete this project. This estimate is based on average removal conditions. Actual cost required for abatement will vary depending on developments unforeseen prior to the beginning of the abatement project.



## **SAMPLE DATA SUMMARY**

Westlink Library Wichita, KS Building: Inspection Date: September 21, 2023

## **Sample Data**

Sample Number	Description	Sample Location	% Asbestos Friable or Non-friable	Condition
1-CT1	2 x 2 ceiling tile	See Location Map	No Asbestos Detected (NAD)	N/A
1-CT2	2 x 2 ceiling tile	See Location Map	NAD	N/A
2-FTa1	Beige w/brown & tan marbling 12" tile	See Location Map	5% Cat. I Non-Friable	Good
2-FTa2	Black mastic	See Location Map	NAD	N/A
2-FTb1	Yellow mastic	See Location Map	NAD	N/A
2-FTb2	Beige w/brown & tan marbling 12" tile	See Location Map	5% Cat. I Non-Friable	Good
2-FTb3	Black mastic	See Location Map	NAD	N/A
3-STa1	Blue stair tread	See Location Map	3% Cat. I Non-Friable	N/A
3-STa2	Brown mastic	See Location Map	NAD	N/A
3-STb1	Blue stair tread	See Location Map	3% Cat. I Non-Friable	N/A
3-STb2	Brown mastic	See Location Map	NAD	N/A
4-SVa1	Black stair landing	See Location Map	NAD	N/A
4-SVa2	Cream mastic	See Location Map	NAD	N/A
4-SVb1	Black stair landing	See Location Map	NAD	N/A
4-SVb2	Cream mastic	See Location Map	NAD	N/A
5-CBa1	Tan cove base	See Location Map	NAD	N/A
5-CBa2	Cream mastic	See Location Map	NAD	N/A
5-CBa3	Brown mastic	Plaster See Location Map	NAD	N/A
5-CBb1	Tan cove base	See Location Map	NAD	N/A
5-CBb2	Cream mastic	See Location Map	NAD	N/A
5-CBb3	Brown mastic	See Location Map	NAD	N/A
6-CTa	1 x 1 ceiling tile	See Location Map	NAD	N/A

## **SAMPLE DATA SUMMARY**

Westlink Library Wichita, KS Building: Inspection Date: September 21, 2023

## **Sample Data**


Sample Number	Description	Sample Location	% Asbestos Friable or Non-friable	Condition
6-CTb	1 x 1 ceiling tile	See Location Map	No Asbestos Detected (NAD)	N/A
7-SRa1	Joint compound	See Location Map	NAD	N/A
7-SRa2	Drywall	See Location Map	NAD	N/A
7-SRb1	Joint compound	See Location Map	NAD	N/A
7-SRb2	Drywall	See Location Map	NAD	N/A
8a	Grout	See Location Map	NAD	N/A
8b	Grout	See Location Map	NAD	N/A
9a	Gray thinset	See Location Map	NAD	N/A
9b	Gray thinset	See Location Map	NAD	N/A
10a1	White caulk	See Location Map	NAD	N/A
10a2	White grout	See Location Map	NAD	N/A
10a3	Tan mastic	See Location Map	NAD	N/A
10b1	Tan ceramic tile	See Location Map	NAD	N/A
10b2	Beige grout	See Location Map	NAD	N/A
10b3	Tan mastic	See Location Map	NAD	N/A
11-FTa1	White w/gray streaks 12" tile	See Location Map	NAD	N/A
11-FTa2	Tan mastic	See Location Map	NAD	N/A
11-FTb1	White w/gray streaks 12" tile	See Location Map	NAD	N/A
11-FTb2	Tan mastic	See Location Map	NAD	N/A
12-CTa	2 x 4 ceiling tile	See Location Map	NAD	N/A
12-CTb	2 x 4 ceiling tile	See Location Map	NAD	N/A
13-FTa1	Blue 12" tile	See Location Map	NAD	N/A
13-FTa2	Yellow mastic	See Location Map	NAD	N/A

## **SAMPLE DATA SUMMARY**

Westlink Library Wichita, KS Building: Inspection Date: September 21, 2023

## **Sample Data**

Sample Number	Description	Sample Location	% Asbestos Friable or Non-friable	Condition
13-FTb1	Blue 12" tile	See Location Map	No Asbestos Detected (NAD)	N/A
13-FTb2	Yellow mastic	See Location Map	NAD	N/A
14-CBa1	Beige cove base	See Location Map	NAD	N/A
14-CBa2	Cream mastic	See Location Map	NAD	N/A
14-CBb1	Beige cove base	See Location Map	NAD	N/A
14-CBb2	Cream mastic	See Location Map	NAD	N/A
15-SC	Sink undercoating	See Location Map	5% Cat. II Non-Friable	N/A
16-Pa	Plaster	See Location Map	NAD	N/A
16-Pb	Plaster	See Location Map	NAD	N/A
16-Pb	Plaster	See Location Map	NAD	N/A
16-Pc	Plaster	See Location Map	NAD	N/A
16-Pc	Plaster	See Location Map	NAD	N/A
17-C	White window caulking	See Location Map	NAD	N/A
18-C	Black door caulking	See Location Map	NAD	N/A
19a	Flashing caulking	See Location Map	NAD	N/A
19b	Flashing caulking	See Location Map	NAD	N/A
20-Ca	Gray door caulking	See Location Map	NAD	N/A
20-Cb	Gray door caulking	See Location Map	NAD	N/A





#### Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 362706 Client: Paradigm Group, LLC

Account Number: B936 Darin Helsel

Date Received: 09/25/2023 1314 N. Oliver, #8200 Wichita, KS 67208

Received By: Baylie Longstreth

Date Analyzed: 09/29/2023 Project: Westlink Library
Analyzed By: Benjamin Hill Project Location: Wichita, KS

Methodology: EPA/600/R-93/116 Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	1-CTa	Homogeneous	White Ceiling Tile	Asbestos Not Present	Glass Fiber 90	Paint
002	1-CTb	Homogeneous	White Ceiling Tile	Asbestos Not Present	Glass Fiber 90	Paint
003	2-FTa	Layered	Beige Floor Tile	Asbestos Present Chrysotile 5	NA	CaCO3 Vinyl
003a		Layered	Black Mastic	Asbestos Not Present	NA	Tar
004	2-FTb	Layered	Yellow Mastic	Asbestos Not Present	NA	Glue
004a		Layered	Beige Floor Tile	Asbestos Present Chrysotile 5	NA	CaCO3 Vinyl
004b		Layered	Black Mastic	Asbestos Not Present	NA	Tar

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

QuanTEM is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested.

NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods.

This report may not be used to claim product endorsement by NVLAP or any agency of the US Government.

This report may not be reproduced except in full, without the written approval of the laboratory.



#### Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 362706 Client: Paradigm Group, LLC

Account Number: B936 Darin Helsel

Date Received: 09/25/2023 1314 N. Oliver, #8200 Wichita, KS 67208

Received By: Baylie Longstreth

Date Analyzed: 09/29/2023 Project: Westlink Library
Analyzed By: Benjamin Hill Project Location: Wichita, KS

Methodology: EPA/600/R-93/116 Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
005	3-STa	Layered	Blue Stair Tread	Asbestos Present Chrysotile 3	NA	Rubber
005a		Layered	Yellow Mastic	Asbestos Not Present	NA	Glue
006	3-STb	Layered	Blue Stair Tread	Asbestos Present Chrysotile 3	NA	Rubber
006a		Layered	Brown Mastic	Asbestos Not Present	NA	Glue
007	4-SVa	Layered	Gray Flooring	Asbestos Not Present	NA	Rubber CaCO3
007a		Layered	Cream Mastic	Asbestos Not Present	NA	Glue CaCO3



#### Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 362706 Client: Paradigm Group, LLC

Account Number: B936 Darin Helsel

Date Received: 09/25/2023 1314 N. Oliver, #8200 Wichita, KS 67208

Received By: Baylie Longstreth

Date Analyzed: 09/29/2023 Project: Westlink Library
Analyzed By: Benjamin Hill Project Location: Wichita, KS

Methodology: EPA/600/R-93/116 Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
008	4-SVb	Layered	Gray Flooring	Asbestos Not Present	NA	Rubber CaCO3
008a		Layered	Cream Mastic	Asbestos Not Present	NA	Glue CaCO3
009	5-CBa	Layered	Brown Cove Base	Asbestos Not Present	NA	CaCO3 Vinyl
009a		Layered	Cream Mastic	Asbestos Not Present	NA	Glue
009ь		Layered	Brown Mastic	Asbestos Not Present	NA	Glue
010	5-CBb	Layered	Brown Cove Base	Asbestos Not Present	NA	CaCO3 Vinyl
010a		Layered	Cream Mastic	Asbestos Not Present	NA	Glue



#### Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 362706 Client: Paradigm Group, LLC

Account Number: B936 Darin Helsel

Date Received: 09/25/2023 1314 N. Oliver, #8200 Wichita, KS 67208

Received By: Baylie Longstreth

Date Analyzed: 09/29/2023 Project: Westlink Library
Analyzed By: Benjamin Hill Project Location: Wichita, KS

Methodology: EPA/600/R-93/116 Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)		Non Fibrous
010ь		Layered	Brown Mastic	Asbestos Not Present	NA		Glue
011	6-СТа	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose Glass Fiber	45 45	Paint
012	6-CTb	Homogeneous	White Ceiling Tile	Asbestos Not Present		45 45	Paint
013	7-SRa	Layered	White Joint Compound	Asbestos Not Present	NA		CaCO3
013a		Layered	White Drywall	Asbestos Not Present	Cellulose Glass Fiber	10 2	Gypsum
014	7-SRb	Layered	White Joint Compound	Asbestos Not Present	NA		CaCO3



#### Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 362706 Client: Paradigm Group, LLC

Account Number: B936 Darin Helsel

Date Received: 09/25/2023 1314 N. Oliver, #8200 Wichita, KS 67208

Received By: Baylie Longstreth

Date Analyzed: 09/29/2023 Project: Westlink Library
Analyzed By: Benjamin Hill Project Location: Wichita, KS

Methodology: EPA/600/R-93/116 Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
014a		Layered	White Drywall	Asbestos Not Present	Cellulose 10 Glass Fiber 2	Gypsum
015	8A	Homogeneous	Brown Grout	Asbestos Not Present	NA	CaCO3 Sand
016	8B	Homogeneous	Brown Grout	Asbestos Not Present	NA	CaCO3 Sand
017	9A	Homogeneous	Gray Thinset	Asbestos Not Present	NA	CaCO3 Sand
018	9B	Homogeneous	Gray Thinset	Asbestos Not Present	NA	CaCO3 Sand
019	10A	Layered	White Caulk	Asbestos Not Present	NA	CaCO3 Binder
019a		Layered	White Grout	Asbestos Not Present	NA	CaCO3 Sand

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

QuanTEM is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested.

NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods.

This report may not be used to claim product endorsement by NVLAP or any agency of the US Government.

This report may not be reproduced except in full, without the written approval of the laboratory.



#### Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 362706 Client: Paradigm Group, LLC

Account Number: B936 Darin Helsel

Date Received: 09/25/2023 1314 N. Oliver, #8200 Wichita, KS 67208

Received By: Baylie Longstreth

Date Analyzed: 09/29/2023 Project: Westlink Library
Analyzed By: Benjamin Hill Project Location: Wichita, KS

Methodology: EPA/600/R-93/116 Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
019Ь		Layered	Tan Mastic	Asbestos Not Present	NA	Glue CaCO3
020	10B	Layered	Tan Ceramic Tile	Asbestos Not Present	NA	Clay Sand
020a		Layered	Beige Grout	Asbestos Not Present	NA	CaCO3 Sand
020b		Layered	Tan Mastic	Asbestos Not Present	NA	Glue CaCO3
021	11-FTa	Layered	White/Gray Floor Tile	Asbestos Not Present	NA	CaCO3 Vinyl
021a		Layered	Tan Mastic	Asbestos Not Present	NA	Glue



#### Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 362706 Client: Paradigm Group, LLC

Account Number: B936 Darin Helsel

Date Received: 09/25/2023 1314 N. Oliver, #8200 Wichita, KS 67208

Received By: Baylie Longstreth

Date Analyzed: 09/29/2023 Project: Westlink Library
Analyzed By: Benjamin Hill Project Location: Wichita, KS

Methodology: EPA/600/R-93/116 Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
022	11-FTb	Layered	White/Gray Floor Tile	Asbestos Not Present	NA	CaCO3 Vinyl
022a		Layered	Tan Mastic	Asbestos Not Present	NA	Glue
023	12-CTa	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 50 Glass Fiber 30	
024	12-CTb	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 50 Glass Fiber 30	
025	13-FTa	Layered	Blue Floor Tile	Asbestos Not Present	NA	CaCO3 Vinyl
025a		Layered	Yellow Mastic	Asbestos Not Present	NA	Glue
026	13-FTb	Layered	Blue Floor Tile	Asbestos Not Present	NA	CaCO3 Vinyl

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

QuanTEM is a NVLAP accredited Testing PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested.

NVLAP accreditation applies only to analysis performed utilizing EPA—40 CFR Appendix E to Subpart E of Part 763 and EPA/600/R-93/116 methods.

This report may not be used to claim product endorsement by NVLAP or any agency of the US Government.

This report may not be reproduced except in full, without the written approval of the laboratory.



#### Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 362706 Client: Paradigm Group, LLC

Account Number: B936 Darin Helsel

Date Received: 09/25/2023 1314 N. Oliver, #8200 Wichita, KS 67208

Received By: Baylie Longstreth

Date Analyzed: 09/29/2023 Project: Westlink Library
Analyzed By: Benjamin Hill Project Location: Wichita, KS

Methodology: EPA/600/R-93/116 Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
026a		Layered	Yellow Mastic	Asbestos Not Present	NA	Glue
027	14-CBa	Layered	Beige Cove Base	Asbestos Not Present	NA	CaCO3 Vinyl
027a		Layered	Cream Mastic	Asbestos Not Present	NA	CaCO3 Glue
028	14-CBb	Layered	Beige Cove Base	Asbestos Not Present	NA	CaCO3 Vinyl
028a		Layered	Cream Mastic	Asbestos Not Present	NA	CaCO3 Glue
029	15-SC	Homogeneous	Purple Sink Undercoat	Asbestos Present Chrysotile 5	NA	CaCO3 Binder



#### Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 362706 Client: Paradigm Group, LLC

Account Number: B936 Darin Helsel

Date Received: 09/25/2023 1314 N. Oliver, #8200 Wichita, KS 67208

Received By: Baylie Longstreth

Date Analyzed: 09/29/2023 Project: Westlink Library
Analyzed By: Benjamin Hill Project Location: Wichita, KS

Methodology: EPA/600/R-93/116 Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
030	16-Pa	Homogeneous	Light Gray Plaster	Asbestos Not Present	NA	Gypsum Sand
031	16-Pb	Layered	Light Gray Plaster	Asbestos Not Present	NA	Gypsum Sand
031a		Layered	Dark Gray Plaster	Asbestos Not Present	NA	Gypsum Sand
032	16-Pc	Layered	Light Gray Plaster	Asbestos Not Present	NA	Gypsum Sand
032a		Layered	Dark Gray Plaster	Asbestos Not Present	NA	Gypsum Sand
033	17-C	Homogeneous	White Caulk	Asbestos Not Present	NA	CaCO3 Binder
034	18-C	Homogeneous	Black Caulk	Asbestos Not Present	NA	CaCO3 Binder



#### Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 362706 Client: Paradigm Group, LLC

Account Number: B936 Darin Helsel

Date Received: 09/25/2023 1314 N. Oliver, #8200 Wichita, KS 67208

Received By: Baylie Longstreth

Date Analyzed: 09/29/2023 Project: Westlink Library
Analyzed By: Benjamin Hill Project Location: Wichita, KS

Methodology: EPA/600/R-93/116 Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
035	19A	Homogeneous	White Caulk	Asbestos Not Present	NA	CaCO3 Binder
036	19B	Homogeneous	Gray Caulk	Asbestos Not Present	NA	CaCO3 Binder
037	20-Ca	Homogeneous	Gray Caulk	Asbestos Not Present	NA	CaCO3 Binder
038	20-Cb	Homogeneous	Gray Caulk	Asbestos Not Present	NA	CaCO3 Binder
	Benjamin	Hill		0/00/0003		

Benjamin Hill, Assistant Laboratory Manager


9/29/2023

Date of Report



362706 PO Box 8200 Wichita, KS 67208 316.239.7097 Fax 316.215.6517

	Address:	/22/23 ty of Wie	Address: Westlink Library  Address: Wichita, KS
	PO #:		Building # Job #:
	Fax:		
	Lead Othe	Test For estos (X)	Type of Analysis  PLM  TEM  Atomic Absorption  TCLP  hr □ 3-Day   55-Day  Other
	SAMPLE NUMBER	TYPE OF CONTAINER	DESCRIPTION OF MATERIAL
1	1-CTa	Plastic Bag	Celling Tila
2	1.CT6	Plastic Bag	k u
3	2-FTa	Plastic Bag	Floor Tile + Mastic
•	2. FTb	Plastic Bag	fl " "
5	3-5Ta	Plastic Bag	Starr Tread
6	3-5Th	Plastic Bag	11 11
7	4.51a	Plastic Bag	Sheet vinyl / Lauding covering
8	4-5Vb	Plastic Bag	n ti d'el
9	5. CBa	Plastic Bag	Cove Base
10	5.CBs	Plastic Bag	11 "
11	Co-CTa	Plastic Bag	Celling Tile
12	6.CT6	Plastic Bag	11 , M
13	7-SRa	Plastic Bag	Drywell & Joint Compound
14	7-5Rh	Plastic Bag	(1) 1/
15	8a	Plastic Bag	Grout
	INSPECTOR/S	AMPLER:	Darin Helsel
	RELINQU	IISHED BY	DATE RECEIVED BY DATE  8/2/22






PO Box 8200 Wichita, KS 67208 316.239.7097 Fax 316.215.6517

	Date: 9	/22/23		Page	: <u>   2 </u> of <u>    3                              </u>					
	Client:	to of W	h)ta Project Addres	i: Wostlank Li ss: Willita KS	brary					
3.0	PO #:		Buildir							
	Phone:		Job #:							
	Fax:									
	Lead Othe	Test For estos 1	r □ 3-Day 🏂-5-Day	Type of Analysis PLM TEM Atomic Absorption TCLP Other	-					
	SAMPLE NUMBER	TYPE OF CONTAINER	DESCRIP MATE							
16	86	Plastic Bag	Grout	out						
17	99	Plastic Bag	Thinset							
18	96	Plastic Bag	11							
19	10 a	Plastic Bag	Grout + Glus							
20	10 h	Plastic Bag	k //							
21	11- FTa	Plastic Bag	Floor tile t.	nastic						
22	11 FT	Plastic Bag	n u	li						
23	12°CTa	Plastic Bag	Ceiling Tile							
24	12° CT h	Plastic Bag	. 11							
25	13- FT.	Plastic Bag	Ploor The +.	mastre						
26	13- FT6	Plastic Bag	11 11	11						
27	14-CBa	Plastic Bag	Corx Base							
28	14-CBb	Plastic Bag	u u							
29	15-SC	Plastic Bag	Sink Coating	S						
30	16-Pa	Plastic Bag	Plaster							
,	INSPECTOR/S	AMPLER:	Darin I	-lelsel	_					
_	RELINQU Paux	JUN	DATE /21/23	RECEIVED BY	DATE					
				*						




362706 PO Box 8200 Wichita, KS 67208 316.239.7097 Fax 316.215.6517

	Date:	7/22/23				Page: <u>3</u> of <u>3</u>
	Client: <u>@ ? </u>	7/22/23 ty of Wic	hita	Project:	Wostlink	Page: 3 of 3 Library KS
	Address.			Address.	Willster	<i>(</i> )
	PO #:			Building	£	
	Phone:			Job #:		
	Fax:			,		
	Lead Othe	Test For estos V	1 0 5		Type of An PLM TEM Atomic Absorption_ TCLP	
	Turnaround:	□ Rush □ 24	hr □3-Day Æ	ζ5-Day 	Other	
	SAMPLE NUMBER	TYPE OF CONTAINER	*	DESCRIPTION MATERIA		
31	16-Ps	Plastic Bag	Plaste			
32	16-Pc	Plastic Bag	11			
33	17-C	Plastic Bag	Caulkin	45		
34	18-6	Plastic Bag	Caulki			
35	19a	Plastic Bag		2 Caulk		
36	196	Plastic Bag	11	11		
37	20-Ca	Plastic Bag	D001 C	aulking		
38	20-66	Plastic Bag	11	4		
		Plastic Bag				
		Plastic Bag				
		Plastic Bag				
		Plastic Bag				
		Plastic Bag				
		Plastic Bag				
		Plastic Bag				
	INSPECTOR/S	AMPLER:		Darin Hel	sel	
(	RELINQU	IISHED BY	DATE 7/22/23		RECEIVED BY	DATE




# FIELD SAMPLE DATA

	$\searrow$			3							E							+	1							
	Cau		П	200							2							-9	M	100	-				T	
	Sept 2			10							+					50		-9	3						7	
23	talia	-	1	+0							+3					11		U	6 00	5					$\dashv$	
/	18 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 -		0.0	F							0				0	7		19		7						
12	10, 5 + 3		۲			2				8	0				2	X		X	3	-					$\dashv$	
9	Olly 3 3t		6	S		0			00	X	0				-			000	X		9				1	
DATE:	1751-3			1		M			y		X				12				00		5				$\dashv$	
DA	AST OFF			Y		O									1			20			1				1	
	MOITA TUSINIA HAYON		'r			6									7			N	00		1					
	The straight		9			4						,5			V			3	768		1				1	
1	The states		200		¢.							4									C				$\dashv$	
10/0	ATO 40 VA		1	_	Ž							2						U	, )		J				$\forall$	
I	AND OUGH		7		N							3						- 7	1		9			П		
0	SALISO ON A OLIVANIA A		7		1							,						1	19		2					
2	TOUTH AND AND		+		(							4 /	1					×	X		×					
INSPTR:	WY CANT		7		9							0	N													
Z	10 NOWILLY		100		57							1	1													
	AOILY TO SALIHO ON TO SALIHO ON TO SALIHO ON THE SALIHO ON		100				П					3	7													
1614	ACIONAL STANDAR STANDA		3		A							9	+													
10	A TO TO			,	0							+	,	N			1									
V	SIGNATURAL SIGNATURA SIGNA	7	5/2	1	0		, x	-				1	7	-			73									
7	AHOOH WAS	3	8		7							2	0	100			la s									
1.h	S. Alling	TX.	)		5		0					1	7	6			Q									
1+50	204 100 00 111 115 15 10 10 10 10 10 10 10 10 10 10 10 10 10	T	F		4		+					1	wetter	0			20									
3	Agar of Million		4		X		4					1	7	1			613									
	\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	7	N				a )	N				-	5	_			xt									
PROJECT	\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	3	X				3	7				X		×			m									
COJ	\$1.50 \\ \tag{\tag{\tag{\tag{\tag{\tag{\tag{	1						1					0				Da.									
PF	THE KET	,					F	×					~				1									
	\$ \$11,0 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	1					0						,				)									
1+9	ASAL ON THE	7					0						60				X									
7	A SALIE						X						1													
3	THE	X											_													
wich													X													
do																										
2.ty																										
1																							3.5			
:E																										
CLIENT:	AREA																									
Ü	AI																									





## SAMPLE LOCATION MAP




Project Westlink Library - Basement	Date 21-Sep-23
Location Wichita, KS	By D. Helsel
Client City of Wichita	Job No.

# SAMPLE LOCATION MAP





# ASBESTOS LOCATION MAP



CREDENTIALS	

Certificate Number: 6979659 Wichita, KS 67211 Phone: (316) 264-7050 Email: training@isienvironmental.com Subpart E, Appendix C, Section 206 of the Toxic Substances Control Act (TSCA Title II), November 3, 2022 has successfully completed a course in and passed the final written exam EPA/AHERA Accreditation for under 40 CFR Part 763, 15 U.S.C. 2646. Missouri Training Provider MO #126 Asbestos Inspector Refresher A Consulting & Facility Support Services Company Environmental with a score of at least 70% for EPA and Missouri Approved Darin Helse Ron Aunquoe, Instructor Expiration: 11/3/2023 215 S. Laura